

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	808	(axial\$4) near3 (force load\$4 strain stress pressure) near3 (screw\$4 bolt nut).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:55
L2	4	1 and (contact\$4) near3 (pin).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:47
L3	6967	(axial\$4) near3 (force load\$4 strain stress pressure) near3 (screw\$4 bolt nut)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:47
L4	215	3 and (contact\$4) near3 (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:56
L5	109	4 and (washer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:56
L6	6	5 and (ultrasonic acoustic\$4 optical\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:49
L7	1949	(axial\$4) near3 (force load\$4 strain stress pressure) near3 (screw\$4 bolt nut).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:58
L8	10	7 and (contact\$4) near3 (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:58
L9	3	8 and (washer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:58

L10	548	73/761.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:58
L11	24	10 and (contact\$4) near3 (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:58
L12	4	11 and (axial\$4) near3 (force load\$4 strain stress pressure) near3 (screw\$4 bolt nut)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:58
L13	5	11 and (axial\$4) near3 (force load\$4 strain stress pressure)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 12:00
L14	122	10 and (axial\$4) near3 (force load\$4 strain stress pressure)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 12:00
L15	6	14 and (pick near3 up)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 12:00
L16	6	15 and (bolt screw\$4 nut)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 12:01

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1928	(limit\$4) near3 (axial\$4) near3 (force load\$4 strain stress pressure)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:24
L2	721	1 and (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:24
L3	62	1 and (contact\$4) near3 (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:33
L4	23	3 and (sens\$4 detect\$4 transducer measur\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:33
L5	548	73/761.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:25
L6	120931	(contact\$4) near3 (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:27
L7	29995	6 and (sensor detector transducer measur\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:28
L8	60	7 and (axial\$4) near3 (force load\$4 strain stress pressure) near3 (screw\$4 bolt)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:32
L9	30	8 and (washer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:36

L10	5	9 and (acoustic\$4 optical\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:30
L11	5055593	"6250863" "5437525" 2003/089177 A1 "84073225" "4419009" "3408310" "19831372" "19954164" "69311479" "0987532"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:32
L12	59	5 and (axial\$4) near3 (force load\$4 strain stress pressure) near3 (screw\$4 bolt)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:39
L13	66	5 and (axial\$4) near3 (force load\$4 strain stress pressure) near3 (screw\$4 bolt nut)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:32
L14	62	13 and (sens\$4 detect\$4 transducer measur\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:33
L15	62	14 and (sens\$4 detect\$4 transducer measur\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:33
L16	4	15 and (contact\$4) near3 (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:36
L17	50	"5699703" "4899591" "4846001"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:35
L18	10	17 and (contact\$4) near3 (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:38
L19	0	18 and (washer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:36

L20	1	16 and (washer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:39
L21	120931	(contact\$4) near3 (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:38
L22	162	21 and (axial\$4) near3 (force load\$4 strain stress pressure) near3 (screw\$4 bolt)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:39
L23	87	22 and (washer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:39
L24	81	23 and (limit\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:40
L25	5	24 and (ultrasonic optical\$4 acoustic\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/28 11:40